



Quality Structures, Inc.

1. We present you with our Valspar WeatherX™ Siliconized Polyester forty (40) year limited past warranty QSI siliconized polyester coil coatings, properly applied to HOG steel (G90+), Zinc-Aluminum Alloy Steel (AZ50+) will meet the following standards:
 - a. For forty (40) years from the date of installation will not crack, check or lose adhesion. This does not include minute fracturing which may occur in proper fabrication of the building parts. Failure due to substrate corrosion is excluded.
 - b. For thirty (30) years our sidewall panels from the date of installation will not chalk in excess of ASTM 0-4214-98 method 0659 a number eight (8) rating. Our roofing panels will not chalk in excess of ASTM 0-4214-98 method 0659 a number (7) rating.
 - c. Color change is determined by the ASTM 02244-02 method. Color change shall be measured on an exposed painted surface that has been cleaned of surface soils and chalk, and the corresponding values measured on the original or unexposed surface. It is understood that fading or color changes may not be uniform, if the surfaces are not equally exposed to the sun and elements. Our sidewall panels will not change color more than five (5) Hunter 6E units. Our roofing panels will not change color more than (6) Hunter 6E units.
2. In case of a complaint, you will provide access to us and assist us as necessary in determining the exact cause of failure. ASTM and NCCA testing procedures will be used.
3. If Paramount Metal's siliconized polyester coil coatings fail to comply with our limited warranty, we will pay for labor and materials reasonably necessary to repaint, repair or replace, at our option, the building part showing the failure.
4. Our Limited warranty does not apply to circumstances which we do not control, including:
 - a. Fire, other casualty, or physical damage.
 - b. Unusual harmful fumes, foreign substances in the atmosphere, standing water, or salt spray.
 - c. Misapplication of Paramount Metal's siliconized coil coatings.
 - d. Mishandled products, any product which has been abused, altered, modified, used in a manner not originally intended.
 - e. Improper Storage.
5. This warranty will apply to metal which is coated and used on property located within the Continental United States.
6. We need to make clear that this is our only warranty concerning these siliconized polyester coil coatings. And that we have no other obligations concerning them. So, please read and understand the following: Except for this warranty, we make no warranty or guarantee (express or implied) with respect to the siliconized polyester panel and trims. Implied warranties, or fitness and merchantability are excluded. Further, we have no other liability with respect to the siliconized polyester panels and trims, whether based on warranty, negligence, or any other legal theory. For example, we have no liability for consequential damages.
7. This is our complete warranty. It sets out all of our obligations regarding Paramount Metal's siliconized polyester coil coatings. It is only for your benefit and is not assignable.

WE BACK OUR BUILDINGS WITH COMMITMENT

SERVICE

- Free Estimates
- On-site Consultations
- Professional
- Courteous Sales Staff
- Fully Licensed And Insured
- Detailed, Efficient Install Crews

DURABILITY

- 60 Yr. Column Warranty
- 40 Yr. Steel Warranty
- Garage Door Warranty
- 5 Yr. Workmanship Warranty
- Builders Risk Policy


QUALITY

- 3-ply Laminated Columns
- #2 And Better Framing Lumber
- All Steel Entry And Garage Doors
- Rust Resistant Painted Steel Exterior
- Screw Application On Steel Exterior

STRENGTH

- Engineered to Meet or Exceed Local Codes
- 115 Mph Wind Load
- 30 Lb. Ground Snow Load
- Trusses Designed for A Ceiling Load
- Roof And Wall Wind Bracing

THE QSI ADVANTAGE



STANDARD FEATURES:

- Continuous Ridge Ventilation
- 29 Gauge Steel on Roof, Sides, Trim
- 4' O/C Trusses @ 4/12 Pitch
- 8' O/C Sidewall Glue/Nail Laminated Columns
- Ledger Loc Fastened 2-Ply Truss Supports
- 2' O/C 2x4 Roof Purlins & Girts
- 115 mph Wind Load
- Treated 2x6 Skirt at Ground Line
- Steel Rodent Guard at Base
- 48" Post Holes with Concrete Footings